

# Jiffler Low Speed Expanfin Mixers



Model # 6

Use key to lower vane: Let shaft stick below hub and tighten screw on flat

Always submerge vanes in product before starting power.

Move around like a paddle: Lightly moving along the bottom, up and down the sides of the container while turning. As the vortex sucks air in the mixer, cut power off and on.

**TO CLEAN:** Wash in solvent with small brush.

**WHEN:** Mixing powder material to liquid, i.e. latex paint, put proper amount of liquid in container, set unit in, add powder and start power

**BONUS FEATURE:** Your drill bearings last 80% longer using our perfectly balanced STIFFLER MIXERS. The slots in the fins screen out the soluble lumps FAST.

**MIXING TECHNIQUES:** On our 7 other sized mixers. Send for our FREE brochure.

## WARNING

- 1. DO NOT use this unit to mix combustibles.**
- 2. Not to be used for food products.**